Noise Monitoring Data - Summary of Construction Noise Monitoring Results (30mins), dB(A)

| NM1A - Slope near the Victoria Shanghai Academy | | | | | | | | | | | |
|---|-------|--------|---------------------------------------|-------------------------------|-------------------------------|---------------------------------|---------------|--|--|--|--|
| Date | Time | | Noise | e Levels, dB(A) | | Limit Level for L _{eq} | | | | | |
| | Start | Finish | Corrected L _{eq} (30min) (1) | Corrected L ₉₀ (1) | Corrected L ₁₀ (1) | Wind Speed (ms-1) | (30min/dB(A)) | | | | |
| 05-Jul-19 | 10:02 | 10:32 | 58.9 | 57.3 | 60.3 | 0.5 | 70 | | | | |
| 11-Jul-19 | 10:30 | 11:00 | 59.2 | 57.6 | 60.7 | 0.4 | 70 | | | | |
| 17-Jul-19 | 10:18 | 10:48 | 58.9 | 57.7 | 60.3 | 0.8 | 70 | | | | |
| 23-Jul-19 | 10:15 | 10:45 | 59.1 | 57.7 | 60.4 | 0.6 | 70 | | | | |
| 29-Jul-19 | 08:45 | 09:15 | 59.5 | 57.8 | 61.1 | 0.3 | 70 | | | | |

| NM2 - Hong Kong Juvenile Care Centre | | | | | | | | | | | |
|--------------------------------------|-------|--------|--------------------------------|------------------------|------------------------|---------------------------------|---------------|--|--|--|--|
| Date | Time | | Noise | e Levels, dB(A) | Wind Cood (ma 4) | Limit Level for L _{eq} | | | | | |
| | Start | Finish | L _{eq} (30min) | L ₉₀ | L ₁₀ | Wind Speed (ms-1) | (30min/dB(A)) | | | | |
| 05-Jul-19 | 09:20 | 09:50 | 51.9 | 48.7 | 53.3 | 0.5 | 70 | | | | |
| 11-Jul-19 | 09:50 | 10:20 | 50.1 | 47.3 | 51.6 | 0.4 | 70 | | | | |
| 17-Jul-19 | 09:35 | 10:05 | 50.7 | 48.0 | 52.1 | 1.0 | 70 | | | | |
| 23-Jul-19 | 09:32 | 10:02 | 49.5 | 46.9 | 50.8 | 0.6 | 70 | | | | |
| 29-Jul-19 | 10:30 | 11:00 | 49.5 | 47.1 | 50.9 | 0.3 | 70 | | | | |

Notes:

(1) A free field correction of +3dB(A) has been made to these measurements as specified in the EM&A Manual and EPD guidelines.