

**Noise Monitoring Data - Summary of Construction Noise Monitoring Results (30mins), dB(A)**

<b>NM1A - Slope near the Victoria Shanghai Academy</b>							
<b>Date</b>	<b>Time</b>		<b>Noise Levels, dB(A)</b>			<b>Wind Speed (ms-1)</b>	<b>Limit Level for L<sub>eq</sub> (30min/dB(A))</b>
	<b>Start</b>	<b>Finish</b>	<b>Corrected L<sub>eq</sub>(30min)<sup>(1)</sup></b>	<b>Corrected L<sub>90</sub><sup>(1)</sup></b>	<b>Corrected L<sub>10</sub><sup>(1)</sup></b>		
05-Aug-20	10:05	10:35	60.4	58.6	62.7	0.7	70
11-Aug-20	10:14	10:44	60.7	58.4	62.3	0.3	70
17-Aug-20	08:35	09:05	60.5	58.6	63.1	0.5	70
27-Aug-20	10:30	11:00	60.5	55.5	63.8	0.5	70

<b>NM2 - Hong Kong Juvenile Care Centre</b>							
<b>Date</b>	<b>Time</b>		<b>Noise Levels, dB(A)</b>			<b>Wind Speed (ms-1)</b>	<b>Limit Level for L<sub>eq</sub> (30min/dB(A))<sup>(2)</sup></b>
	<b>Start</b>	<b>Finish</b>	<b>L<sub>eq</sub>(30min)</b>	<b>L<sub>90</sub></b>	<b>L<sub>10</sub></b>		
05-Aug-20	09:20	09:50	49.6	46.6	51.8	0.4	70
11-Aug-20	09:30	10:00	51.2	49.0	52.7	0.3	70
17-Aug-20	10:30	11:00	50.8	47.6	53.0	0.5	70
27-Aug-20	09:45	10:15	49.9	45.7	51.8	0.2	70

(1) A free field correction of +3dB(A) has been made to these measurements as specified in the EM&A Manual and EPD guidelines.