

NM1A - Slope near Victoria Shanghai Academy (VSA)					
Date	Time		Construction Noise Monitoring Results (dB(A))		
	Start	Finish	*Correction L_{eq30min}	*Correction L10	*Correction L90
22-Jul-16	13:36	14:06	69.4	71.5	62.0
28-Jul-16	10:57	11:27	67.9	69.0	58.5
3-Aug-16	9:16	9:46	67.7	70.0	61.0
9-Aug-16	13:16	13:46	65.5	67.5	58.5
15-Aug-16	13:01	13:31	57.0	59.5	52.0

(*) A façade correction of +3dB(A) has been added according to acoustical principles and EPD guidelines

NM2 - Hong Kong Juvenile Care Centre (HKJCC)					
Date	Time		Construction Noise Monitoring Results (dB(A))		
	Start	Finish	L_{eq30min}	L10	L90
22-Jul-16	15:00	15:30	60.4	61.5	55.0
28-Jul-16	9:38	10:08	61.3	63.5	57.5
3-Aug-16	10:13	10:43	60.3	62.5	52.0
9-Aug-16	14:18	14:48	60.5	61.5	55.0
15-Aug-16	13:47	14:17	59.2	62.5	52.0