

NM1A - Slope near Victoria Shanghai Academy (VSA)									
Date	Time		Construction Noise Monitoring Results (dB(A)						
	Start	Finish	*Correction L _{eq30min}	*Correction L10	*Correction L90				
19-Sep-16	09:42	10:12	65.2	68.0	58.5				
29-Sep-16	10:13	10:43	64.1	66.5	59.5				
04-Oct-16	13:14	13:44	63.0	65.5	53.5				
14-Oct-16	09:27	09:57	64.0	65.0	59.0				

^(*) A façade correction of +3dB(A) has been added according to acoustical principles and EPD guidelines

NM2 - Hong Kong Juvenile Care Centre (HKJCC)									
Date	Time		Construction Noise Monitoring Results (dB(A)						
	Start	Finish	$ m L_{eq30min}$	L10	L90				
19-Sep-16	11:09	11:39	62.4	62.5	55.0				
29-Sep-16	09:14	09:44	59.0	61.0	54.5				
04-Oct-16	13:59	14:29	60.4	60.0	54.0				
14-Oct-16	10:23	10:53	61.2	62.0	58.5				