

Appendix E Representative Photos for Implementation of Mitigation Measures



OP01 Sensitive Design and Disposition – Color palette of the design was mostly in subdued tones. Floor and walls were painted with non-reflective finishing.




OP02 Compensatory Tree Planting – General view of whip trees newly planted.



OP03 Enhancement Planting – Additional trees and shrubs were planted along the pedestrian walkway.



OP04 Green Roofs and Vertical Greening – General view of green roof and vertical green in establishment.



OP05 Reversion of Flamingo Pond – General view



OP06 Responsive Lighting Design – General view of lighting design with appropriate level of lighting to reduce potential impact