

**Noise Monitoring Data - Summary of Construction Noise Monitoring Results, dB(A)**

<b>NM1A - Slope near the Victoria Shanghai Academy</b>						
<b>Date</b>	<b>Time</b>		<b>Noise Levels, dB(A)</b>			<b>Limit Level for Leq (dB(A))</b>
	<b>Start</b>	<b>Finish</b>	<b>Corrected Leq(30min) <sup>(1)</sup></b>	<b>Corrected L<sub>90</sub> <sup>(1)</sup></b>	<b>Corrected L<sub>10</sub> <sup>(1)</sup></b>	
03-Dec-20	08:27	08:57	59.4	55.2	61.8	70
09-Dec-20	10:15	10:45	60.3	59.2	63.3	70
15-Dec-20	10:10	10:40	59.3	57.9	60.8	70
21-Dec-20	10:05	10:35	59.6	56.9	62.3	70
30-Dec-20	10:10	10:40	60.4	58.2	62.3	70
05-Jan-21	10:10	10:40	60.6	58.4	62.4	70
11-Jan-21	10:20	10:50	60.2	56.7	62.5	70
21-Jan-21	10:10	10:40	59.7	56.5	62.1	70
27-Jan-21	09:50	10:20	60.5	58.8	62.3	70
02-Feb-21	10:20	10:50	60.1	56.1	62.2	70
08-Feb-21	10:15	10:45	61.1	56.0	64.1	70
17-Feb-21	10:35	11:05	60.3	57.1	62.6	70
23-Feb-21	08:33	09:03	60.0	57.7	61.7	70

<b>NM2 - Hong Kong Juvenile Care Centre</b>						
<b>Date</b>	<b>Time</b>		<b>Noise Levels, dB(A)</b>			<b>Limit Level for Leq (dB(A)) <sup>(2)</sup></b>
	<b>Start</b>	<b>Finish</b>	<b>L<sub>eq</sub>(30min)</b>	<b>L<sub>90</sub></b>	<b>L<sub>10</sub></b>	
03-Dec-20	10:10	10:40	50.7	48.8	53.2	70
09-Dec-20	09:30	10:00	50.9	44.9	54.0	70
15-Dec-20	09:20	09:50	52.1	50.4	53.4	70
21-Dec-20	09:20	09:50	50.7	46.0	53.5	70
30-Dec-20	09:25	09:55	50.5	48.3	52.3	70
05-Jan-21	09:25	09:55	53.8	50.5	56.1	70
11-Jan-21	11:00	11:30	52.2	48.8	54.4	65
21-Jan-21	09:25	09:55	52.1	50.8	54.2	65
27-Jan-21	10:35	11:05	52.4	50.0	54.0	70
02-Feb-21	09:30	10:00	52.1	49.5	53.6	70
08-Feb-21	09:30	10:00	51.4	47.8	53.0	70
17-Feb-21	09:50	10:20	51.6	47.6	53.6	70
23-Feb-21	10:25	10:55	52.0	50.7	53.0	70

**Notes:**

- (1) A free field correction of +3dB(A) has been made to these measurements as specified in the EM&A Manual and EPD guidelines.
- (2) Acceptable Noise Levels for school should be reduced to 65 dB(A) during examination period.