

**Noise Monitoring Data - Summary of Construction Noise Monitoring Results, dB(A)**

<b>NM1A - Slope near the Victoria Shanghai Academy</b>						
<b>Date</b>	<b>Time</b>		<b>Noise Levels, dB(A)</b>			<b>Limit Level for Leq (30min)/dB(A)<sup>(2)</sup></b>
	<b>Start</b>	<b>Finish</b>	<b>Corrected Leq(30min)<sup>(1)</sup></b>	<b>Corrected L90<sup>(1)</sup></b>	<b>Corrected L10<sup>(1)</sup></b>	
6-Dec-18	10:00	10:30	59.3	55.2	61.6	70
12-Dec-18	11:00	11:30	59.7	58.4	61.1	70
18-Dec-18	10:00	10:30	61.9	59.9	64.0	70
24-Dec-18	13:40	14:10	59.3	57.9	61.0	70
27-Dec-18	14:40	15:10	58.9	57.7	60.3	70
4-Jan-19	10:30	11:00	60.8	57.4	62.5	70
10-Jan-19	9:30	10:00	61.0	58.1	62.8	70
16-Jan-19	10:00	10:30	61.3	59.0	63.1	70
22-Jan-19	9:30	10:00	61.6	59.5	63.4	70
28-Jan-19	9:35	10:05	59.4	58.1	60.9	70
8-Feb-19	9:57	10:27	58.9	56.8	60.9	70
14-Feb-19	10:00	10:30	59.9	57.8	61.9	70
20-Feb-19	10:10	10:40	59.8	58.4	61.3	70
26-Feb-19	14:30	15:00	59.0	57.8	60.5	70

<b>NM2 - Hong Kong Juvenile Care Centre</b>						
<b>Date</b>	<b>Time</b>		<b>Noise Levels, dB(A)</b>			<b>Limit Level for Leq (30min)/dB(A)<sup>(2)</sup></b>
	<b>Start</b>	<b>Finish</b>	<b>L<sub>eq</sub>(30min)</b>	<b>L<sub>90</sub></b>	<b>L<sub>10</sub></b>	
6-Dec-18	9:20	9:50	52.4	48.9	54.8	70
12-Dec-18	10:20	10:50	52.3	50.9	53.9	70
18-Dec-18	9:20	9:50	52.2	50.9	53.7	70
24-Dec-18	13:10	13:40	50.7	49.5	52.3	70
27-Dec-18	14:00	14:30	51.1	49.8	52.3	70
4-Jan-19	9:50	10:20	50.7	49.4	52.1	70
10-Jan-19	8:50	9:20	50.2	47.0	52.0	70
16-Jan-19	9:20	9:50	52.2	50.3	53.8	70
22-Jan-19	8:50	9:20	52.1	50.9	53.5	70
28-Jan-19	8:55	9:25	50.4	49.0	51.9	70
8-Feb-19	9:15	9:45	47.1	44.5	49.4	70
14-Feb-19	9:20	9:50	52.7	51.0	55.0	70
20-Feb-19	9:30	10:00	52.4	50.1	53.8	70
26-Feb-19	13:50	14:20	50.1	48.6	51.4	70

**Notes:**

- (1) A free field correction of +3dB(A) has been made to these measurements as specified in the EM&A Manual and EPD guidelines.
- (2) Acceptable Noise Levels for school should be reduced to 65 dB(A) during examination period.